

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY
CONDITION CERTIFICATE.**

Latter No: 808

Date: 06.07.2021

It is certified that an inspection team headed by Executive Engineer (Name of Officers with designation) from P.H.Division, Buxar (Name of Department/Office) inspected the SARASWATI VIDYA MANDIR, Ahirauli Buxar (Name & Address of the School) on 03.07.2021 and found that SARASWATI VIDYA MANDIR (Name of School) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T.Govt.

The Above valid for a period of :- Six Months

Signature with Seal: [Signature]

Name : EXECUTIVE ENGINEER
P.H. DIVISION, BUXAR

Designation : _____

Revised
06/07/21

Bandana
06/07/21
AE, Buxar

To

Saraswati Vidya Mandir
Ahirauli, Buxar
Buxar - 802101

पञ्चेश प्रकाश सिंह
सचिव
सरस्वती विद्या मन्दिर
अहिरौली, बक्सर

Principal
Saraswati Vidya Mandir
Ahirauli, Buxar