

Letter No.....

Date:.....

PUBLIC HEALTH ENGINEERING DEPARTMENT, BUXAR
 DISTRICT LEVEL WATER TESTING LABORATORY, (DLWTL)
Water Quality Test Report
 Division Name: BUXAR

District Name: BUXAR						Parameters															Format: I	
Sl. No.	Block	Panchyat	Village	Ward no.	Location of Source	PH	Turb.	EC	TDS	TH	Ca	Mg	Cl	Alka.	Fe	NO ₃	SO ₄	F	As(Raw)	Total Coli	REMARKS	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
1	BUXAR	AHIRAUULI	AHIRAUULI	NH:84	SARASWATI VIDYA MANDIR, (HAND PUMP)	7.7	1	440.0	286	200	72	30.7	30	260	0.9	35	55	0.5	0.005	(-VE)		
2	BUXAR	AHIRAUULI	AHIRAUULI	NH84	SARASWATI VIDYA MANDIR, (BORING)	7.5	2	426.2	277	240	56	44.2	20	230	0.3	30	25	0.4	BDL	(-VE)		
Unit						NTU	umho/cm	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l	mg/l		
Desirable Limit						5.5-8.5	5.0	500	200	75	30	250	200	1.0	45	200	1.0	0.01				
Max. permissible limit						NR	NR	2000	600	200	100	1000	500	NR	NR	400	1.5	NR				

Remarks: Fit for drinking.

Ravi Shankar
 05/07/21
 Chemist
 P.H. Division, Buxar

Bandana
 06/07/21
 AE Buxar

S. K. Singh
 Executive Engineer
 P.H. Division, Buxar

सरस्वती विद्या मन्दिर
 गविव
 सरस्वती विद्या मन्दिर
 अहिरीली, बक्सर

Principal
 Saraswati Vidya Mandir